

HISTORIC AMERICAN ENGINEERING RECORD  
INDEX TO PHOTOGRAPHS

HAER  
VA  
8-STAY.V,  
3-

KERR'S CROSSING BRIDGE

HAER No. VA- 101

(Bridge No. 6027)

Spanning Christian's Creek at Virginia Route 907

Staunton Vicinity

Augusta County

Virginia

Photographer: Rob Tucher

April 1994

VA-101- 1	APPROACH FROM EAST, VIEW WEST
VA-101- 2	NORTH ELEVATION, VIEW SOUTH
VA-101- 3	SOUTH ELEVATION, VIEW NORTH
VA-101- 4	DECK AND APPROACH FROM WEST, VIEW EAST
VA-101- 5	DECK, VIEW WEST
VA-101- 6	BEAM AND STRINGER SYSTEM UNDERNEATH, VIEW WEST
VA-101- 7	BEAM AND STRINGER SYSTEM UNDERNEATH, VIEW EAST
VA-101- 8	WEST ABUTMENT, SOUTH SIDE, VIEW NORTH
VA-101- 9	DETAIL OF SHOE, EAST ABUTMENT, NORTH SIDE, VIEW SOUTH
VA-101-10	DETAIL OF VERTICALS, PANEL BRACING, RAILING, VIEW NORTHEAST
VA-101-11	DETAIL OF TOP END CONNECTION U1, NORTHEAST CORNER, VIEW NORTH
VA-101-12	DETAIL OF TOP CHORD CONNECTION U2, NORTHEAST CORNER, VIEW NORTH
VA-101-13	DETAIL OF LOWER CHORD CONNECTION L5, VIEW SOUTHEAST